

**Addendum No. 2 to IFB 15-73**



**CITY OF SOMERVILLE, MASSACHUSETTS**  
**Department of Purchasing**  
**JOSEPH A. CURTATONE**  
**MAYOR**

To: All Parties on Record with the City of Somerville as Holding IFB 15-73,  
Bleacher Repair and Renovation at Somerville High School

From: Michael Richards, Procurement Analyst

Date: February 27<sup>th</sup>, 2015

Re: Amend Scope of Work, Bid Pricing Sheet, and Rule for Award

**Addendum No. 1 to IFB 15-73**

---

**Please acknowledge receipt of this Addendum by signing below and including this page in your non-technical proposal package. Failure to do so may subject the proposer to disqualification.**

**NAME OF COMPANY / INDIVIDUAL:** \_\_\_\_\_

**ADDRESS:** \_\_\_\_\_

**CITY/STATE/ZIP:** \_\_\_\_\_

**TELEPHONE/FAX/EMAIL:** \_\_\_\_\_

**SIGNATURE OF AUTHORIZED INDIVIDUAL:** \_\_\_\_\_

**Please acknowledge receipt of any and all Addendums (if applicable) by signing below and including this form in your proposal package. Failure to do so may subject the proposer to disqualification.**

**ACKNOWLEDGEMENT OF ADDENDUMS:**

**Addendum #1** \_\_\_\_\_ **#2** \_\_\_\_\_ **#3** \_\_\_\_\_ **#4** \_\_\_\_\_

## **Addendum No. 2 to IFB 15-73**

### **1. Amended Scope of Work**

The following scope of work will consist of all items required in the Base Bid:

#### **Scope of Work**

##### **Targeted Repairs to Model 2400 Wall Attached Powered Bleachers**

- Replace all Power Track III motor; supply and install 4 Power Track IV motors
- Supply and install 12 pairs of tier catches/row locks
- Supply and install 1 male control plug
- Supply and install 4 skirt board locks and spacers – 1 per section
- Replace damaged/missing frame wheels as needed
- Clean interlocking and moving frame components of the steel understructure, including:
  - Cantilever arms, lower interlocking frame track, and tier catches
- Supply 1 new Pendant Control
- Replace and/or tighten hardware on all sections of the bleacher, as needed
- Re-stress decks and grease interlocking and moving parts as needed
- Adjust and align bleacher for proper operation
- Inspect and clean lower track obstructions
- Replace all skirt board hinges
- Replace 1 skirt board
- Replace 1 24"x8' plywood deck
- Adjust existing seat modules, specifically at the section breaks

##### **Installation of E-Z Fit Safety End Rails**

The installation of safety rails on the end sections of the bleachers is required to make the equipment code compliant. The following estimated quantities are requested as part of the installation of safety rails on the end sections of the bank of bleachers:

- 32- E-Z Fit Safety End Rails
- 32 – Tie Straps
- 32 – Hardware Packages
- 2 – E-Z Fit Safety Top End Rails
- 8 – Double Post Clamps
- 2 – Single Post Clamps
- 2 – Rail Brackets
- 2 – Hardware Packages

---

The following scope of work will consist of all items in the Add-Alternate Bid:

#### **Scope of Work**

- Full deck section connectors – upgrade section connectors to the Full Deck Connector

## Addendum No. 2 to IFB 15-73

### 2. Amended Bid Pricing Sheet

BASE BID	
Targeted Bleacher Repair	
Price in words	
Price in numbers	\$
Installation of Safety Rails	
Price in words	
Price in numbers	\$
<b>Total Pricing:</b>	\$
ADD-ALTERNATE BID	
Full Deck Section Connectors	
Price in words	
Price in numbers	\$
<b>Total Pricing:</b>	\$

### 3. Amended Rule for Award

One contract will be awarded to the responsible and eligible bidder offering the lowest total base bid pricing. Add-alternates will be considered in the order they are listed.